

Conservation of Architectural Timberwork of the Kandyan Period

This work is my own work and has not been
previously submitted to this University or to another
University or other qualification.

V. Amarasinghe
Name of Student

A thesis presented to the
University of Moratuwa, for the Master of Science degree in
Architectural Conservation of Monuments and Sites.
 University of Moratuwa, Sri Lanka.
Electronic Theses & Dissertations
www.lib.mrt.ac.lk

V.Y. Amarasinghe
ACOMAS, Faculty of Architecture, University of Moratuwa.
25.8.2010

Declaration

I declare that this Thesis represents my own work and that it has not been previously included in reports submitted to this University or to another institution for a degree, postgraduate diploma or other qualification.

UOM Verified Signature

.....
Name of Student / Signature

UOM Verified Signature

.....
Course Director (ACOMAS)



Prof. S. Manawadu
Department of Architecture
University of Moratuwa
Electronic Theses & Dissertations
www.lib.mrt.ac.lk



UOM Verified Signature

Abstract

The Kandyan period buildings which are of predominantly timber construction form a valuable part of our cultural heritage. Conservation of these structures require special skills and expertise to consolidate them without damaging their authenticity. Degeneration of the timberwork of these buildings is caused by the activity of decay causing agencies and the changes instigated during the periodic renewal process.

The objective of this thesis was to identify the nature and causes of degeneration seen on the timber elements of these buildings and to provide recommendations for the conservation of the same. The study was based on a qualitative approach and relied primarily on observations made at site, on records and documentation relating to the conservation of the structures and on past examples and experience.

The findings show that the degeneration of the Kandyan period timberwork, was instigated often by the combined or interrelated action of human, biological and climatic factors. The necessity was seen for preventive measures to prolong the life of timber elements to minimize the need for renewal, and for research to be carried out to find methods and material that are economical and adaptable to local conditions, based on their performance in the past. Using traditional concepts, methods and techniques for this end, seems to be the most valid solution.

Key words

Kandyan period buildings – The buildings recorded as existing at the time the British took over the ancient Kandyan kingdom of Sri Lanka, in 1815 A.D.

Conservation – The process through which the material, historical and design integrity of built heritage are prolonged through carefully planned interventions

Traditional – The passing down of elements of a culture from generation to generation / a time honoured practice

Authenticity – Is considered to mean genuine in terms of the physical fabric of the heritage property regarding its form and design, material and substance, location and setting.

Degeneration – The state or process of being or becoming degenerate; decline or deterioration in terms of material and physical content of buildings

Acknowledgements

I would like to express my sincere gratitude to my Thesis Supervisor, Professor T.K.N.P. De Silva who has helped me immensely with my research material, has given me valuable insights, and whose encouragement and guidance enabled me to complete this thesis.

I also have to express my heartfelt gratitude to my course director, Professor. S.Manawadu for all the encouragement and guidance given, during the most critical time of writing this thesis to enable me to complete and present it successfully.

I have to specially mention with the most sincere gratitude my (past) ACOMAS course director Archt. C.J. De Saram whose encouragement and guidance gave me the much needed inspiration and confidence during the most critical, and the most difficult stages of writing this thesis.

I am also deeply grateful to my External Thesis Supervisor, Archt. J. Herath for all the encouragement, constructive suggestions and advice he has given me throughout the writing of this thesis.



University of Moratuwa, Sri Lanka.

Electronic Theses & Dissertations

www.lib.mrt.ac.lk

I am most indebted to the panel of judges at the Viva voc examination, for all the valuable and constructive criticisms and advice given, which has enabled me to complete and re-structure the work successfully, and present it in conformity to the accepted University Standards.

I am also deeply indebted to Mr. V.P.A. De Mel, Staff Technical Officer of the Conservation Laboratory (ACOMAS) who has been of immense help to me at all times.

Lastly, I wish to express my gratitude to all those who helped me in numerous ways, making this thesis possible. I also owe my sincere gratitude to the Department of ACOMAS, for granting permission to write this thesis, which has been a most unique and interesting experience.

List of Illustrations

Page no.

1.The Medawala vihara was restored by King Kirti Sri	6
2. The front of kings palace, Kandy provided by Davy.(1821)	8
3.The Godamunne rest hall	8
4.The Dodamwala devale	9
5.Audience hall of kings at Kandy	13
6.Left-The Vahalkada at kundasale Right-Vahalkada at Embekke	13
7. Ambalama at Dolapihilla	14
8.Left - The temple at Bihalpola, Right- The temple at Meepitiya	15
9. Left- The granary at Embekke, Above - The entrance to the granary	16
10.A walauwa as it existed in early 20 th century (Lewis, 1908)	16
11.The Paththirippuwa	17
12.Above -The kings palace in Kandy,Below -Cave temple at Degaldoruwa	17
13. Top -The shrine at Niyamgampaya, Below-The Pansala at Bihalpola	18
14. Above- The Banashalawa at Maathgamuwa, Below – The Banashalawa at Suriyagoda	19
15. Above-The roofed chaitya at Gadaladeniya, Below-A small deistic shrine in Kandy	20
16. A roofed wall found in the Kandy temple complex	20
17.The Audience hall , as seen from the west	22
18.Interior view of the structure.	24
19.Right-Interior view of the structure.	25
20.Above-Corner rafters are laid in a radiating fashion	25
21.Right -Roof eave detail	26
22.Dutch map of 1765 (Seneviratna 1993,p.76)	26
23.The structure as seen in early 20 th century	27
24.Above-The ancient tiled floor ,Below - Metal plates had been inserted	28
25.Above-British period structure ,Left -The joint between the old and new sections	29
26.New column footing	30
27.The rectangle of carved beams	31
28.Square holes have been patched up	31
29.Left- An angular beam parallel to the lower	32
30.Ground floor Plan of Audience hall	33
31.Nontraditional joints have been inserted in beams	34
32.Longitudinal Section through Audience hall	34
33.Layout of roof beams and cross section of Audience hall	35
34.The rectangle of carved beams	37
35.The 19 th century illustration	37
36.Interior view of roof at northern and southern ends.	38
37.Right-Interior view of Audience hall in early 20 th century	39
38.Right-The Audience hall seen from the Northern end.	40
39.Below-Decay by termites seen on beams	41
40. Timber cover plate has got detached exposing the steel bolts	42
41.Right-Cracks on beam has been aggravated by metal hook	43
42.The Digge seen from the front	46
43.Inside view. Entrance to inner shrine seen at the back	46
44.Carved pekada detail	44
45.Above-Interior view, Right-Rafters are made to join in a radiating fashion	47
46.Right-Front corner Roof beam detail, Below-Rafters are intricately carved at the eave	48
47.Right,Above-View of Digge, Right,Below- front corner of digge as seen in early 20 th century	49
48.Above-Embekke digge prior to the intervention, Right , below-The stone door frame	50
49.The digge structure after restoration in 1947	51
50. Variations in carving motifs seen in the box like central facets of columns	51
51.Half lotus forms are seen carved in one column	53
52.Right-Valley gutters have been used to connect the roofs of Digge and inner shrine	54
53.Plan and section of Embekke Digge	55
54.Left -The double rows of columns along northern side	56
55.The granite base of column	57
56.Right-Carving on central panel of older column	57
57.Below-Filling of carved area has been well executed	58
58.Above--Tiered beams are cut in a stepped fashion along roof	60
59.The few older Carved beams can be differentiated	60
60.The columns in the north east corner appear to be more exposed to weathering	61
61.Horizontal cracks on pekada	61
62.Carved beams resting on the walls of inner chamber	62
63.The metal plates inserted to strengthen the rafters	62

	Page no.
64. The ambalama seen from front	64
65. Wider seats have been provided around the sides	66
66. Right-The entrance recess seen from inside	66
67. Right-The external columns, Below-The king post and supporting beam	67
68. The structure as it was found at the time of the initial intervention	68
69. The snapped King post is seen in this picture taken before the intervention	69
70. The carvings in central box like panels of columns	69
71. The structure after conservation by the department of archaeology in 1962	70
72. Some of the pekada provided during the intervention are carved in out line only	70
73. Below-The cobra pattern seen on column	71
74. Left-Different detailing is seen in the carving of top panels of column	72
75. Right- Rafter details at the eave and corner joint of wall plate	72
76. Left- Internal column, Below-Badly disfigured external column	73
77. Most of the old carved columns have been scraped systematically	73
78. Plan and Section	74
79. Right- The column with large cavity.	76
80. Above- Earliest recorded plan of the structure, Left- Patched up section near entrance	76
81. The carvings seen in box like facets	77
82. Unconventional design motifs are seen in timber elements	78
83. Right-The split in ground beam	79
84. Recent filling work of cavities in column	80
85. The crack lines are seen developing on the pekada	81
86. The rear king post has developed a number of crack lines	83
87. The small ambalama seen from the south-west	84
88. Right -Interior view of structure, looking towards the west	86
89. The internal ground beams are raised higher off the ground	86
90. Left-Simple volute shaped pekada have been provided for the external corner columns	87
91. The roof is supported on two lines of timber columns	88
92. According to the pictures taken before the intervention in 2005	88
93. The difficulty in accessing the site has obviously been a major cause of cost escalations	89
94. Right-The ground beams placed on stone supports	90
95. Mortise hole found in column	91
96. Left-New external ground beams appear to have been prepared first for a column	91
97. Above-Crudely repaired old column	92
98. Cracks are seen on carved boss	92
99. Above-The external ground beams are too low to sit	93
100. Plan and Section	94
101. Left-The smaller set of pekada are found in the north-west corner	95
102. Column carving details.	96
103. The corner joint between the new wall plates	97
104. Above-Mildew stains seen on the pekada	99
105. The filling compound used on the old cracked column	100
106. The temple on pillars seen from the south	102
107. The ground beams and slab from underneath	104
108. Above - The arched doorway to shrine, Right-The carved columns	105
109. Right-The upper roof corner detail, Below- Lower roof corner detail	106
110. Painted ceiling and beams of circumbulatory passage	107
111. Painted ceiling in the interior of shrine	107
112. The structure as found in 1972	108
113. The column pekada had been partly encased by the timber boarding of first floor	108
114. The decayed wall plate and carved ends of the older ground beams	109
115. Pekada are seen covered in paint in the picture taken before 1972	110
116. The differences in carving style in columns	111
117. Plaster has cracked along a beam	112
118. The decayed area of ceiling close to earthen wall of shrine	112
119. The brick pillar is seen under a cross beam	113
120. Ground floor plan and Section	113
121. Weak joint seen in ground beam	114
122. Metal door to enter stairway	114
123. Upper floor Plan	115
124. The grooved beam between columns	116
125. Note the difference in rafter end detail	118
126. Timber bearing scars of termite decay are seen in the cavity under roof	118
127. Cracks in columns have been filled	119
128. Right-Cracking along grain lines, seen in beams	120

	Page No.
129. Right-Cracking seen on rafter end	121
130. Decayed ceiling panel (in Circumbulatory passage)	121
131. The temple seen from the west	123
132. Entrance steps leading to the temple	123
133. Above-The ground beam ends ,below,right – Porch extension	125
134. Right-The carved door jamb, Below-Column with pekada in the porch	126
135. Right-The hip rafter is almost triangular in section	127
136. Right- The structure seen after the fire on 19.5.1997	128
137. Signs of charring seen on the reused external floor boards	128
138. Right-The tooth relic building at the rear of temple	129
139. Above-The makara thorana above the entrance,Left-The main entrance to the temple	130
140. Above-The floor boards are heavily decayed,below-Growth of lichen seen on timber	131
141. Left- End splits seen on ground beam	131
142. Section	132
143. Plans	133
144. The proximity of the adjoining building on the east has a degenerating affect	134
145. Right-The charred column	135
146. Carving work on new columns	136
147. The roof seems to have been the most affected element in the fire	137
148. Right- Termite attacked ground beams	138
149. Gaps are seen in the new floor planks	139
150. Right-Checks and splits are seen developing on the new carved columns of the porch	140
151. The wall plate has been cut and wedges have been inserted in an effort to adjust its shape	141
152. A neatly executed kutti-malli joint in external wall plate	141
153. The Ambalamas are especially vulnerable. The structure at Waturakumbura	145
154. Lamps being lit seen inside Bihalpola shrine	146
155. Positive effects of the raised plinth and overhanging eave seen in pavilion structures	148
156. Comparison between Bihalpola and Bingiriya.	149
157. Right- Old filling work seen at Embekke	155
158. An embankment with planting may have a positive effect on panavitiya	158
159. At Suriyagoda part of the ancient banamaduwu has been modernized	160
160. An enclosing wall was found at the stone pillared temple at Ambudugala	163
161. At Hindagala the roof was changed to its present double pitched form	164
162. A typical rolling programme of preventive maintenance	165
163. At Padeniya , the external row of columns were added	166
164. For carved elements like this dipping in preservative solution would be the best alternative	168
165. Right-Metal ties used for strengthening cracked beam at the vahalkada at Dodamwela..	170
166. Dilution of carved detail	171
167. Painted pekada (embedded in wall) seen at Suriyagoda	176
168. The white substance seen in carving in Kandewela	177

List of Maps and Site Plans

	Page no.
1. Location Plan for Case Studies	21
2. Site Plan - Audience Hall	23
3. Site Plan - Embekke Drummers hall	45
4. Site Plan - Panavitiya Rest Hall	65
5. Site Plan - Kandewela Rest Hall	85
6. Site Plan - Bingiriya Temple on Pillars	103
7. Site Plan - Bihalpola Temple on Pillars	124

Contents

Page no.

Introduction

1

Chapter One

Conservation of Kandyan Period timber buildings

-Historical background

4

1.1. Historical Background to the conservation of Timber buildings in Sri Lanka

4

1.1.1. Traditional Approach 5

1.1.2. Colonialist Approach 7

1.1.3. Post Independence Approach 10

1.2. Traditional building types of the Kandyan period

12

1.2.1. Pavilion (Mandapa) type structures built in timber 13

1.2.2. Pavilions built on timber frame resting on stone supports 13

1.2.3. Timber framed wattle and daub structures resting on stone Supports 14

1.2.4. Timber roofed structures 16

Chapter Two

Identification of the causes of degeneration of Kandyan period



University of Moratuwa, Sri Lanka.

Electronic Theses & Dissertations

timber buildings - Case studies
www.lib.mrt.ac.lk

21

2.1. Case Study 1 - Audience hall

22

2.1.1. Location 22

2.1.2. Building description 22

2.1.3. History/Past interventions 26

2.1.4. Signs of degeneration observed on building 30

2.1.5. Causes for the degeneration of building 36

2.2. Case Study 2 - Embekke Drummers hall

44

2.2.1. Location 44

2.2.2. Building description 44

2.2.3. History/Past interventions 48

2.2.4. Signs of degeneration observed on building 53

2.2.5. Causes for the degeneration of building 56

2.3. Case Study 3 - Panavitiya Rest hall

64

2.3.1. Location 64

2.3.2. Building description 64

2.3.3. History/Past interventions 68

2.3.4. Signs of degeneration observed on building 71

	Page no.
2.3.5. Causes for the degeneration of building	76
2.4. Case Study 4 - Kandewela Rest hall	84
2.4.1. Location	84
2.4.2. Building description	84
2.4.3. History/Past interventions	88
2.4.4. Signs of degeneration observed on building	90
2.4.5. Causes for the degeneration of building	93
2.5. Case Study 5 - Bingiriya Temple on pillars	102
2.5.1. Location	102
2.5.2. Building description	102
2.5.3. History/Past interventions	108
2.5.4. Signs of degeneration observed on building	111
2.5.5. Causes for the degeneration of building	114
2.6. Case Study 6 - Bihalpola temple on pillars	123
2.6.1. Location	123
2.6.2. Building description	123
2.6.3. History/Past interventions	127
2.6.4. Signs of degeneration observed on building	129
2.6.5. Causes for the degeneration of building	134
Chapter Three	
An Overview on the factors which had an effect on the degeneration of buildings and recommendations for conservation	142
3.1. Factors which had an effect on the degeneration of buildings	142
3.1.1. Location, setting and climate	142
3.1.2. Ownership and use	144
3.1.3. Design of Building elements	148
3.1.4. Conservation programme and approach	153
3.1.5. Material and techniques used during interventions	155
3.2. Recommendations for the conservation of buildings	157
3.2.1. Location, setting and climate	157
3.2.2. Ownership and use	159
3.2.3. Design of Building elements	161

	Page no.
3.2.4. Conservation programme and approach	163
3.2.5. Material and techniques for conservation	167
3.3. Applicability of traditional principles and techniques in conservation work	172
3.3.1. Maintaining and developing forest reserves	173
3.3.2. Use of traditional timber conversion and processing methods	174
3.3.3. Reviving traditional building techniques and treatments	176
Conclusion	179
Bibliography	181
Index of Scientific names for trees	184



University of Moratuwa, Sri Lanka.
 Electronic Theses & Dissertations
www.lib.mrt.ac.lk