

**RECOMMENDATION OF MAINTENANCE
SCHEDULE BY ANALYSING CONDITION
MONITORING TEST DATA OF GENERATORS**

Kelum Niroshan Senarathne

Index No : 109256 K



University of Moratuwa, Sri Lanka.
Electronic Theses & Dissertations
www.Degree.MU.ac.lk Master of Science

Department of Electrical Engineering

University of Moratuwa
Sri Lanka

April 2015

Declaration, copyright statement and the statement of the supervisor

I declare that this is my own work and this thesis/dissertation does not incorporate without acknowledgement any material previously submitted for a Degree or Diploma in any other University or institute of higher learning and to the best of my knowledge and belief it does not contain any material previously published or written by another person except where the acknowledgement is made in the text.

Also, I hereby grant to University of Moratuwa the non-exclusive right to reproduce and distribute my thesis/dissertation, in whole or in part in print, electronic or other medium. I retain the right to use this content in whole or part in future works (such as articles or books).



K. N. Senarathne

Date:

The above candidate has carried out research for the Masters Dissertation under my supervision.

.....
Supervisor:

.....
Date:

Prof. J.P. Karunadasa

Abstract

Condition monitoring is a modern engineering tool developed to asses the status of valuable properties. The thesis describes generator stator winding condition by analyzing three main test procedures, called DC ramp test, Partial discharge test and vibration test. Above mentioned tests were conducted on three main power station attached to Thermal complex of Ceylon Electricity Board in Sri Lanka.

Off line DC ramp test is conducted on the generator stator winding by applying ramped DC voltage. Accordingly total leakage current is plotted against the applied voltage. After obtaining final leakage profile, analyzing is done according to the winding insulation type. Partial Discharge test equipment is installed to monitor electrical discharges due to voids of the stator winding. Those discharges will degrade the insulation and, if not corrected, repeated discharges will eventually erode a hole through the stator winding insulation, leading to failure. Therefore detection and analyzing methodologies discuss throughout the thesis. Finally discuss the importance of introducing PD detection system for identified generators which are more severe effect to generator and the power system.

Some rotating machinery problems show themselves as excessive vibration. It can be identified using online vibration measurement, because vibration signatures show machine's mechanical and electrical conditions. Also it can be identified possible effect to the stator winding.



University of Moratuwa, Sri Lanka

Electronic Theses & Dissertations

During the case study, 19 generators were considered in plant wise to access the condition using above mentioned tools. Tests were carried out to identify the status of generator stator winding and it helps to categorize the degree of acceptability of present condition and planned their preventive maintenance to improve the reliability and availability. Finally preventive maintenance schedule is introducing parallel to the present maintenance plan.

Acknowledgement

I would like to extend my sincere gratitude to my supervisor, Prof. J.P. Karunadasa for his great insight guidance in this study. Also, as the head of the department, he gave me the helping hand for all the laboratory experiments carried out in the Department of Electrical Engineering. In addition, I must appreciate the coordinator of the Post Graduate Division of the Department of Electrical Engineering, Dr. Asanka Rodrigo for all the assistance given to me.

In addition, I shall be grateful to the maintenance staff of thermal power stations of Ceylon Electricity Board who authorized and help me to attend condition monitoring tests and providing details of present maintenance practices. Also I must appreciate Assert Management Thermal Complex Electrical branch and Mechanical branch who provided the test instrument and necessary guiding to conduct my research.

University of Moratuwa, Sri Lanka.
Finally I should thank all my colleagues for who haven't been mentioned personally for making this study a success. www.mrt.ac.lk

1 Table of Contents

1	CONDITION MONITORING.....	1
1.1	Introduction	1
1.1.1	Trend monitoring.....	2
1.1.2	Condition checking.....	2
1.2	Condition Monitoring test procedures.....	2
1.2.1	DC Ramp test	3
1.2.2	Partial discharge testing	4
1.2.3	Vibration monitoring testing	6
1.3	Construction of Stator Winding	6
1.3.1	Thermal Stress	8
1.3.2	Electric Stress	9
1.3.3	Ambient Stress (Factors).....	9
1.3.4	Mechanical Stress	10
1.4	Case study	11
1.4.1	Kelanithissa Power Station.....	11
1.4.2	Sapugaskanda Power Station.....	12
1.4.3	Kelanitissa Combined Cycle Power Station	12
2	DC RAMP TEST	13
2.1	Instrumentation and Preparation.....	13
2.2	Test Voltage.....	14
2.3	Test Procedure.....	14
2.4	Test Analyzing Methodology	15
2.4.1	Capacitive Current (I_C).....	16
2.4.2	Conduction Current (I_R)	16
2.4.3	Surface leakage Current (I_L)	16
2.4.4	Polarization Current (I_p).....	17
2.5	Classification of leakage current profile.....	17
3	PARTIAL DISCHARGE TEST	19
3.1	Instrumentation and Preparation	19
3.1.1	Coupling Capacitor	19
3.1.2	Resistive Thermal Detectors (RTDs) Module for PD Detection.....	20
3.2	PD Analyzing Methodology	22
3.2.1	Negative polarity	23
3.2.2	Positive polarity	23
3.3	Advantages of PD Continuous Monitoring.....	25
4	VIBRATION MONITORING TEST	27
4.1	Instrument and Preparation.....	27
4.1.1	Vibration Sampling Points	28
4.1.2	SKF GX Series MX 70 Microlog Data Analyzer.....	28

4.1.3	SKF CMSS2200- Data acquisition equipment	29
4.2	Vibration Analyzing Methodology	30
4.2.1	Identifying of the Machine's Running speed.....	33
4.2.2	Misalignment.....	33
4.2.3	Imbalance.....	34
4.2.4	Mechanical looseness.....	36
4.2.5	Bearing defects	37
5	PREVENTIVE MAINTENANCE SCHEDULING.....	38
5.1	Sapugaskanda power station.....	38
5.1.1	PIELSTICK plant	38
5.1.2	Case study of PIELSTICK plant.....	39
5.1.3	MAN plant	46
5.1.4	Case study of MAN plant.....	47
5.2	Kelanithissa Power Station.....	54
5.2.1	Kelanitissa Small Gas Turbine	54
5.2.2	Case study of small gas turbine	55
5.2.3	Kelanitissa Gas Turbine No7.....	61
5.2.4	Case study of Gas Turbine No7	62
5.3	Kelanithissa Combined Cycle Power Station.....	68
5.3.1	Gas turbine of Kelanitissa Combined Cycle Plant.....	68
5.3.2	Case study of Gas turbine.....	70
5.3.3	Steam turbine of Kelanitissa Combined Cycle Plant.....	73
5.3.4	Case study of Steam Turbine	74
6	CONCLUSION.....	77
6.1	Review of Sapugaskanda Power Station	77
6.1.1	Review of maintenance schedule of Pielstick plant	77
6.1.2	Review of maintenance schedule of MAN plant.....	78
6.2	Review of Kelanitissa Power Station	78
6.2.1	Review of maintenance schedule of Small Gas Turbine	79
6.2.2	Review of maintenance schedule of Fiat Generator.....	79
6.3	Review of Kelanitissa Combined Cycle Power Station.....	80
6.3.1	Review of maintenance schedule of Gas Turbine Generator.....	80
6.3.2	Review of maintenance schedule of Steam Turbine Generator	81
7	REFERENCE	i
8	APPENDIX - A	iii
.	APPENDIX - B.....	v
.	APPENDIX - C.....	vii

LIST OF FIGURE

Figure 1:1 Cross section of a coil winding with an air pocket.....	5
Figure 1:2 Cross section of the coil in a stator slot	7
Figure 1:3 Physical cross section of winding	7
Figure 1:4 Generator life span with operating temperature	8
Figure 2:1 Instrumentation layout of DC ramp test.	13
Figure 2:2 DC ramp test result of DG04 of Sapugaskanda Power Station	15
Figure 2:3 Classification of leakage current profiles	15
Figure 2:4 Classification of total leakage with insulation condition	17
Figure 3:1 Layout of PD monitoring sensors.....	19
Figure 3:2 Coupling Capacitor	20
Figure 3:3 RTD or RC temperature sensor mounting	20
Figure 3:4 Interface terminal board for Temperature and PD monitoring.....	21
Figure 3:5 PD test sample	22
Figure 3:6 Classification positive & negative polarity.....	23
Figure 3:7 Relationship of electrons flow in positive and negative polarity cycle.....	24
Figure 4:1 Vibration monitoring process	27
Figure 4:2 Vibration sampling position.....	28
Figure 4:3 SKF GX Series Microlog Data Analyzer	29
Figure 4:4 SKF CMSS2200- Data acquisition equipment and structural layout.....	29
Figure 4:5 Vibration profile of Generator 05, Sapugaskanda plant	30
Figure 4:6 Angular misalignment.....	33
Figure 4:7 Parallel Misalignment	34
Figure 4:8 One side heavy Spot of the rotor.....	35
Figure 4:9 Either side heavy Spots of the rotor	35
Figure 5:1 DC ramp test before maintenance of G4, Sapugaskanda plant	40
Figure 5:2 DC ramp profile of B Phase of G4, Sapugaskanda plant.....	41
Figure 5:3 Dry ice cleaning of G4, Sapugaskanda Power Station.....	42
Figure 5:4 DC ramp test after maintenance of G4, Sapugaskanda plant	42
Figure 5:5 DC ramp B phase result after maintenance of G4, Sapugaskanda	43
Figure 5:6 Pielstick plant generator with Diesel engine	44
Figure 5:7 Vibration test of G 3, Sapugaskanda Power Station.....	45
Figure 5:8 DC ramp test result before maintenance of G7, Sapugaskanda plant	48
Figure 5:9 Before maintenance of DC ramp, Phase Y of G7, in Sapugaskanda plant.....	49
Figure 5:10 DC ramp test result after maintenance of G7, in Sapugaskanda plant.....	50
Figure 5:11 DC ramp test after maintenance of phase Y of G7, Sapugaskanda plant.....	50
Figure 5:12 Layout of MAN plant Genset.....	52
Figure 5:13 Vibration profile of Generator 05, Sapugaskanda plant.....	52
Figure 5:14 DC ramp test before maintenance of GT 3, Kelanitissa plant	56
Figure 5:15 DC ramp test before maintenance of R phase of GT 3, Kelanitissa plant.....	57
Figure 5:16 DC ramp test after maintenance of GT 3, in Kelanitissa plant.....	58
Figure 5:17 Layout of KPSGT02, Kelanitissa plant	59
Figure 5:18 Vibration profile of Gas turbine 05, Kelanitissa plant.....	60
Figure 5:19 PD Symptoms observed from GT 07 on 2014.08.13.....	63
Figure 5:20 DC ramp test before maintenance of KPSGT 7, Kelanitissa plant	64
Figure 5:21 Dry ice cleaning work of KPSGT7 during 96,000 Rhr maintenance	65
Figure 5:22 DC ramp test result after maintenance of KPSGT7, Kelanitissa plant	65
Figure 5:23 Kelanitissa Gas turbine No 07	66
Figure 5:24 Vibration test result of Gas turbine Generator No 07 of Kelanitissa plant.....	67
Figure 5:25 PD Symptoms observed from KCCPGT on 2014.08.08.....	70
Figure 5:26 Before maintenance of GT of Kelanitissa Combined cycle power station.....	72
Figure 5:27 DC ramp test before maintenance of Gas turbine generator, Kelanitissa Combined Cycle power station.....	73
Figure 5:28 DC ramp test before maintenance of Steam Turbine Generator ,Kelanitissa Combined cycle power station	75
Figure 5:29 DC ramp test before cleaning of Steam turbine generator.	75

LIST OF TABLE

Table 4-1 Classification of vibration harmonics.....	31
Table 5-1 Generator maintenance Details	39
Table 5-2 DC ramp result which was obtained from Phase B.	43
Table 5-3 Classification of vibration harmonics.....	45
Table 5-4 Routine maintenance plane of MAN plant	47
Table 5-5 Comparison with DC ramp result of Phase Y, Generator 07	51
Table 5-6 Classification of harmonics	53
Table 5-7 Routine maintenance shedhule of Kelanitissa small GTs.....	55
Table 5-8 Classification of harmonics	60
Table 5-9 OEM Recommended Maintenance Schedule.....	62
Table 5-10 Comparison of DC ramp result	64
Table 5-11 Classification of harmonic component	67
Table 5-12 OEM Recommended Maintenance Schedule.....	69
Table 5-13 Reference vibration level of Kelanitissa combined cycle plant.....	71



University of Moratuwa, Sri Lanka.
Electronic Theses & Dissertations
www.lib.mrt.ac.lk