


## References

- [1] Nippon Koei Co. Ltd. "Master Plan Study for Development of the Transmission System of the Ceylon Electricity Board, Final Report Appendix", January 1998.
- [2] Anderson, J.G. et al. "Transmission Line Reference Book-345 kV and Above", 2<sup>nd</sup> ed. Ch 12. Palo Alto, California: Electric Power Research Institute, 1982.
- [3] Burgsdorf, V. V., "Lightning Protection of Overhead Transmission Lines and Operating Experience in the USSR," Proceedings CIGRE, Report 236 (1958).
- [4] AIEE Committee Report "A Method for Estimating Lightning Performance of Transmission Lines", AIEE Transactions Pt. III, 69, 1187 – 1196 (1950).
- [5] E.R. Whitehead. "Protection of Transmission Lines," Lightning. Vol. 2, Edited by R.H. Golde, New York: Academic Press, 1977.
- [6] M. Darveniza, F. Popolansky, E.R. Whitehead. "Lightning Protection of UHV Transmission Lines," Electra. No. 41, July 1975.
- [7] G.W. Brown. "Lightning Performance - Shielding Failures Simplified", IEEE Transactions on Power Apparatus and Systems, Vol. PAS-97, 1978.
- [8] G.D. McCann. "The Effect of Corona on Coupling Factors Between Ground Wires and Phase Conductors," AIEE Transactions on Power Apparatus and Systems", Vol. 62, pp. 818-826, 1943.
- [9] R.R. Love. "Improvements on Lightning Stroke Modeling and Applications to the Design of EHV and UHV Transmission Lines", M.Sc. Thesis, University of Colorado, 1973.  
  
www.lib.mrt.ac.lk
- [10] R.B. Anderson, A.J. Eriksson. "Lightning Parameters for Engineering Applications". Pretoria, South Africa: CSIR, June, 1979, Report ELEK 170.
- [11] Sargent, M.A. and Darveiniza, M., "Tower Surge Impedance", IEEE Transactions, Power Apparatus and Systems, 88, pp 680-687 (1969).
- [12] M. Darveniza, et al. "Modeling For Lightning Performance Calculations", IEEE Transactions on Power Apparatus and Systems. Vol. PAS 98, 1979.
- [13] "CEB Statistical Digest-2005", Statistical Unit, Commercial & Corporate Branch, Distribution Region-3, PO Box 540, Colombo 02, Sri Lanka.
- [14] Gi-ichi, Ikeda, "Report on Lightning Conditions in Ceylon, and Measures to Reduce Damage to Electrical Equipment", Asian Productivity Organization Project TES/68, 1969.