

3. The priority given to the health and safety of the workers were very low. Protective clothing (aprons, gloves) has to be provided to the workers who are exposed to acids, which on prolong exposure can cause harmful health effects. The adequate ventilation of the factory buildings improves the working conditions
4. Treatment technology is available but the success depends on the selection of the treatment components with sizes.

References

- 1 D.C. BLACKLEY, Polymer lattices science and technology, 1982, 64 P 65
- 2 SLS 819: 1988-Tolerance limits for effluents from raw rubber industry
- 3 INDUSTRIAL POLLUTION GUIDELINE: Book no.2, Concentrated Latex Industry, Central Environmental authority Publications, 1992/93 , 5P
- 4 ECO TRADE MANUAL, Environmental challenges for exporting to the European Union, August 1998 , 98 P 100
- 5 INDUSTRIAL POLLUTION GUIDELINE: Book no.1, Natural rubber industry, Central Environmental authority Publications, 1992 / 93.
- 6 SENEVIRATNE, W.M.G., Cost effective wastewater treatment system based on high rate anaerobic septic tank digester coupled with aerobic mechanisms for the treatment of rubber & allied industrial effluents, Rubber Research Institute of Sri Lanka, 1980.
7. O.S.PEIRIS, A hand book of rubber culture and processing, Rubber Research Institute of Sri Lanka, 1970
- 8 BEVERLY THORPE, Citizen's guide to cleaner production, 1980

