# A CRITICAL EVALUATION OF WASTEWATER DISPOSAL FACILITIES IN SELECTED UNDERSERVED SETTLEMENTS IN THE COLOMBO MUNICIPAL AREA AND RECOMMENDATIONS FOR IMPROVEMENTS

## Abdul Gaffoor Irshadh

### 08/10363



Thesis submitted in partial fulfillment of the requirements for the degree Master of Science

Department of Civil Engineering

University of Moratuwa Sri Lanka

April 2013

### **DECLARATION**

I declare that this is my own work and this thesis does not incorporate without acknowledgment any material previously submitted for a degree or a diploma in any of the university or institute of higher learning and to the best of my knowledge and belief it does not contain any material previously published or written by another person except where the acknowledgement is made in the text.

Also, I hereby grant to University of Moratuwa the non-exclusive right to reproduce and distribute my dissertation, in whole or in part in print, electronic or other medium. I retain the right to use this content in whole or part in future works (such as articles or books).

University of Moratuwa, Sri LaPata:
Electronic Theses & Dissertations
www.lib.mrt.ac.lk

The above candidate has carried out research for the Masters thesis under my supervision.

Signature of the supervisor: Date:

## **ABSTRACT**

Sanitation has become a problem in many developing countries. According to reports from WHO and UNICEF in 2012 about 2.6 billion people around the world lack this facility and that counts to half the developing world lack even simple improved latrine. An underserved settlement (USS) is where communities live lacking access to basic services. Half the Colombo city's population lives in the USSs. It is essential to provide better sanitation and improved wastewater (WW) disposal systems.

To assess the type of water supply available, prevailing wastewater disposal methods and the sanitation system and to identify the types of toilets, six USSs were selected considering the municipal districts and the different types of WW disposal systems prevailing in the Colombo Municipal area, and surveyed.

The results were evaluated against the standards provided by Joint Monitoring Programme of the WHO.

During the study period there were 371 households (HHs) in six selected USSs. About 90% of the HHs has individual water connection.

One for each 10 to 12 HHs that have individual septic tanks, and minimum one cluster of HHs that use a common septic tank, from each USS were chosen as representatives for detail study in the aspects of water usage and WW disposal. The results for satisfactory septic tanks are varying from 40% to 100%. Nevertheless none of the household has septic system and that results in diverting the septic tank effluent to the storm water drains ending up polluting the water bodies.

WWW.lib.mrt.ac.lk

In the toilet usage, only in one USS all the HHs have access to the improved sanitation facility. Except one USS in the other five, 50% of the HH which have improved toilets are named using unimproved toilets, because sharing.

Only in two USSs less than 15% HHs directly dispose WW to the storm water drains.

It is commendable that approximately 75% of the HHs, which has permanent housing, is willing for sanitation improvements.

Based on these results recommendations are given to enhance the sanitation in the USSs.

## ACKNOWLEDGEMENT

First my gratitude is forwarded to the International Development Research Centre (IDRC) of Canada for their financial support for the course and the research.

Very special thanks belong to my supervisor, Prof. (Mrs.) N. Ratnayake (Senior professor, University of Moratuwa) and the Course Coordinator Dr. Jagath Manathunga (Senior Lecturer, University of Moratuwa) and all my tutors specially Dr. Mahesh Jayaweera, (Senior Lecturer, University of Moratuwa), for their inspiring lecturing and for their continuous guidance and endless support during my study and research. They were kind enough to find time for my thesis among their busy schedule of work.

During data collection in the underserved settlement, officials attached to the Drainage division of Colombo Municipal Council were very generous to cooperate with me. They do deserve my thanks. Moratuwa, Sri Lanka.

Electronic Theses & Dissertations

Special thanks with love and gratified owes to my wife for the sacrifice for my higher education.

I would like to thank my late father who was my inspiration and my mother who has been my strength.

# TABLE OF CONTENTS

	Page	
Declaration		i
Abstract		
Acknowledgment		
Table of Content		V
List of figures		ii
List of Tables		X
List of Abbreviations	X	$\Pi$
List of Appendices	X	II
1. Introduction	0	1
1.1 Background	0	1
1.1.1 Geography	0	1
1.1.2 Political environment	0	1
1.1.3 Sanitation	0	1
1.2 Statement of Problem	0:	2
1.3 Objective and Scope of the Study	0.	3
1.4 Layout of the Report	0	4
2. The Literature Review	0.	5
2.1 Definition of Terms	0.	5
2.2 Research methods	0	7
2.2.1 Participant observation or atu	wa, Sri Lanka. 0	7
2.2 Surveys and Interviews 2.3 Technologies	Dissertations	
2.3 Technologies www.lib.mrt.ac.lk	0	8
2.3.1 Available on site sewerage dis	sposal facilities 0	8
2.3.1.1 Septic tank	0	
2.3.1.2 Two compartment seption	e tanks.	9
2.3.1.3 Three compartment sept	ic tank	
2.3.1.4 Determination of working	ng capacity of septic tanks	0
2.3.1.5 Up flow filter	1:	
2.3.1.6 Settled sewerage	1	
3 Methodology	1.	5
3.1 Selection of Samples	1	6
3.1.2 The Municipal Districts	1	6
3.2 Disposal methods	1	
3.3 Characteristic of Underserved Settle		
3.4 The Selection	1	8
3.4.1 The Selection of individua	-	
for detail study	2	0

4.	Results and Analysis 4.1 Aliwatte USS 4.1.1 Description of Study Area 4.1.1.1 Location	22 22 22 22
	<ul> <li>4.1.2 Results of the Household Survey</li> <li>4.1.2.1 population</li> <li>4.1.2.2 Household Information</li> <li>4.1.2.3 Types of water sources, Availability and Coverage</li> <li>4.1.2.4 Existence &amp; condition of Latrines</li> </ul>	23 23 24 24 25
	4.1.3 Description of Sanitation and Wastewater disposal 4.1.3.1 Problems with Sanitation and Wastewater disposal	27 30
	<ul> <li>4.2 The Settlement, Bodhiraja Mawathe</li> <li>4.2.1 Description of Study Area</li> <li>4.2.1.1 Location</li> <li>4.2.2 Results of the Household Survey</li> <li>4.2.2.1 population</li> <li>4.2.2.2 Household Information</li> <li>4.2.2.3 Types of water sources, Availability and Coverage</li> <li>4.2.2.4 Existence &amp; condition of Latrines</li> </ul>	30 30 30 31 31 32 32 33
	4.2.3 Description of Sanitation and Wastewater disposal U1.2.2.1 Problems with Sanitation and Wastewater disposal Electronic Theses & Dissertations 4.3.1 Watter Stuert Streett ac.lk 4.3.1 Description of Study Area 4.3.1.1 Location 4.3.2 Results of the Household Survey 4.3.2.1 Population 4.3.2.2 Household Information 4.3.2.3 Types of water sources, Availability and Coverage 4.3.2.4 Existence & condition of Latrines  4.3.3 Description of Sanitation and Wastewater disposal 4.3.3.1 Problems with Sanitation and Wastewater disposal 4.3.3.2 Methods to Improve Sanitation and Wastewater disposal	35 39 40 40 40 41 41 42 43 44 45 45
	<ul> <li>4.4 183, 186 Watte Aramaya Place</li> <li>4.4.1 Description of Study Area</li> <li>4.4.1.1 Location</li> <li>4.4.2 Results of the Household Survey</li> <li>4.4.2.1 population</li> <li>4.4.2.2 Household Information</li> <li>4.4.2.3 Types of water sources, Availability and Coverage</li> <li>4.4.2.4 Existence &amp; condition of Latrines</li> </ul>	47 47 47 48 48 48 50 51

4.4.3	Description of Sanitation and Wastewater disposal 4.4.3.1 Problems with Sanitation and Wastewater disposal	51 54
	Description of Study Area 4.5.1.1 Location	55 55 55 56 56 56 58 58
4.5.3	Description of Sanitation and Wastewater disposal 4.5.3.1 Problems with Sanitation and Wastewater disposal	59 61
5 watte	Swarna road	61
4.6.2	4.6.1.1 Location Results of the Household Survey 4.6.2.1 Population 4.6.2.2 Household Information 4.6.2.3 Types of water sources Availability and Coverage 4.6.2.4 Existence & condition of Latrines Lectronic Theses & Dissertations	61 63 63 63 64 65
, , ,	4.6.3.1 Problems with Sanitation and Wastewater disposal	68
Evalua	ation of Underserved Settlements compared to improved	68 68
5.1 5.2 Sumr The (	Conclusions Recommendations mary Table Questionnaire	74 74 76 78 80 82 88
	00 Watte 4.5.1 I 4.5.2  4.5.3  5 watte 4.6.1 I 4.6.2  Summ Evalua sanitat  Concl 5.1 5.2  Sum The O	4.4.3.1 Problems with Sanitation and Wastewater disposal  00 Watte, Hadhbodhiya, 4.5.1 Description of Study Area 4.5.1.1 Location 4.5.2 Results of the Household Survey 4.5.2.1 Population 4.5.2.2 Household Information 4.5.2.3 Types of water sources, Availability and Coverage 4.5.2.4 Existence & condition of Latrines  4.5.3 Description of Sanitation and Wastewater disposal 4.5.3.1 Problems with Sanitation and Wastewater disposal 5 watte Swarna road  4.6.1 Description of Study Area 4.6.1.1 Location 4.6.2 Results of the Household Survey 4.6.2.1 Population 4.6.2.2 Household Information  1.6.2.3 Types of water sources Availability and Coverage 1.6.3 Types of water sources Availability and Coverage 1.6.3 Pescription of Sanitation and Wastewater disposal 4.6.3 Problems with Sanitation and Wastewater disposal 4.6.3 Problems with Sanitation and Wastewater disposal 4.6.3 Problems with Sanitation and Wastewater disposal 5 Summary 6 Evaluation of Underserved Settlements compared to improved sanitation  Conclusions & Recommendations 5.1 Conclusions

# LIST OF FIGURES

	Page
Figure 2.1: Schematic diagram of septic tank	10
Figure 2.2: Up-flow system	13
Figure 2.3: The schematic diagram of settled sewer and house connection	14
Figure 3.1: Flow diagram of research methodology	15
Figure 3.2: Administrative Districts of Colombo Municipal Council	17
Figure 4.1: The Location map of Aliwatte, Mattakkuliya	
Figure 4.2: Photos of different houses, Aliwatte, Mattakkuliya	24
Figure 4.3: The sketch of the USS Aliwatte, Mattakkuliya.	26
Figure 4.4: Picture of a Common toilet with common septic tank	27
Figure 4.5: Location map of the settlement, Bodhiraja Mawathe	31
Figure 4.6: The sketch of the USS Bodhiraja Mawatha	34
Figure 4.7: The commode fixed toilet, Bodhiraja Mawatha	35
Figure 4.8: The septic tank overflow pipe to the Storm water drain,  Bodhiraja Mawathay of Moratuwa, Sri Lanka.	37
Figure 4.9 The arrangement of the house in the USS, Bodhiraja Mawatha www.lib.mrt.ac.lk Figure 4.10: Location map of 34 watte, Stuert Street	38 40
Figure 4.11: Sketch of 34 Watte, Stuert Street	41
Figure 4.12: The housing either side of the concrete passage,	42
34 Watte, Stuert Street	
Figure 4.13: Water sealed type squatting pan	44
Figure 4.14: Picture of a Common toilet at 34 Watte, Stuert Street	45
Figure 4.15: Location map of 183,186 watte, Aramaya Place	47
Figure 4.16: The housing & concrete passage, 183,186 watte, Aramaya Pla	ace 49
Figure 4.17: Sketch of 183,186 Watte, Aramaya Place	50
Figure 4.18: Storm water drain at 183,186 watte Aramaya Place	54
Figure 4.19: Location map of 300 Watte, Hathbodhiya	55
Figure 4.20 : Sketch of 300 watte, Hathbodhiya	56
Figure 4.21: Existing housing at 300 watte, Hathbodhiya	57

	Page
Figure 4.22: Flow of WW in storm water drain, 300 Watte, Hathbodhiya	60
Figure 4.23: Location map of 65 watte, Swarna Road	62
Figure 4.24 : Sketch of 65 Watte, Swarna Road	63
Figure 4.25: Existing housing at 65 Watte, Swarna road	64



# LIST OF TABLES

Table 2.1: Improved and Not Improved Sanitation Technologies	Page 6
Table 3.1: Selected Under Served Settlements	19
Table 3.2: The selected Individual & Common septic tanks for further study	21
Table 4.1: Consumption of water by selected HH in Aliwatte, Mattakkuliya	25
Table 4.2: Wastewater generation of selected HH in Aliwatte	28
Table 4.3: Results of minimum satisfactory requirement for septic tanks	29
according to Sri Lanka standard 745 : Part 1 : 2004	
Table 4.4: Consumption of water by selected HH in The Settlement,	33
Bodhiraja Mawathe	
Table 4.5: Wastewater generation of selected HH in The Settlement	36
Bodhiraja Mawathe	
Table 4.6: Results of minimum satisfactory requirement for septic tanks	39
according to Sri Lanka Standard 745 : Part 1 : 2004	
Table 4.7: Consumption of water by selected HH in 34 Watte, Stuert Street University of Moratuwa, Sri Lanka.	43
Table 4.8: Consumption of water by selected HH in 183,186 watte,	51
Aramaya Placew.lib.mrt.ac.lk	
Table 4.9: Wastewater generation of selected HH	52
Table 4.10: Results of minimum satisfactory requirement for septic tanks	53
according to Sri Lanka standard 745 : Part 1 : 2004	
Table 4.11: Consumption of water by selected HH in the USS	58
Table 4.12: Wastewater generation of selected HH	59
Table 4.13: Results of minimum satisfactory requirement for septic	61
tanks according to Sri Lanka standard 745 : Part 1 : 2004	
Table 4.14: Consumption of water by selected HH in the USS	65
Table 4.15: Wastewater generation and influent to the septic tanks in the selection	66
Table 4.16: Results of minimum satisfactory requirement for septic tanks	67
according to Sri Lanka standard 745 : Part 1 : 2004	

P	age
Table 4.17: Availability of WW disposals by USS compared to satisfactory methods	69
Table 4.18: Availability of Toilets by USS with classification.	70
Table 4.19: Details of selection and satisfaction for septic tanks in the study area Table 4.20: Details of Type of houses and Residences	71 72
Table 4.21: Willingness for contribution for the Improvement of sanitation	73



# LIST OF ABBREVIATIONS

Abbreviation Description

CMC Colombo Municipal Council

Code Sri Lanka Standard 745: part 1:2004

HH Household

JMP Joint Monitoring Programme

USS Underserved Settlement

UNICEF United Nations Children's Fund

WHO World Health Organization

WW Wastewater



# **List of Appendices**

Appendix	Description	Page
Appendix A	Summary Table	80
Appendix B	The Questionnaire	82
Appendix C	Results of the Survey	88

