

EXISTENCE OF HOME IN SETTLEMENT
A STUDY OF POST DISASTER HOUSING AT
"TOTAGAMUWA"

H.D.A. Aseni

A Dissertation Submitted to in partial fulfillment of the Requirements for the degree of Master of Science
In Architecture

Department of Architecture

University of Moratuwa

Sri Lanka

October 2006

95728

List of contents

Acknowledgement

Contents

List of illustrations

Introduction

The study

Need of the study

Aims and Objectives of study

Method of study

Scope and limitation

Chapter 01

1. Housing as a need of human existence

1.1. Need of "shelter"	1
1.1.1. "Shelter" as Dwelling	3
1.1.2. Meaning of Dwelling	4
1.1.3. Function of Dwelling	5
1.2. Home As center of Human Existence	6
1.2.1. Home in Built	6
1.2. 1. 1. Cent e r	6
1.2.1.2. Enclosure	7
1.2.1.3. continuity	8

EXISTENCE OF HOME IN SETTLEMENT

A STUDY OF POST DISASTER HOUSING AT "TOTAGAMUWA"

List of Contents

1.3. psychological attributes of Home	9
1.3.1. personalization	9
1.3.2. sense of belongings	10
1.3.3. self esteem	11
1.3.4. status	11
1.3.5. identity	12
1.4 . Physical attributes of Home	13

- 1.4.1. orientation 13
- 1.4.2. territoriality 14
- 1.4.3. security 14
- 1.4.4. privacy 15
- 1.5. formation of
- 1.5.1. Socio-Cultural Background 17

Chapter 02

2. Disaster as event of social, physical and imbalance

- 2.1.1. man made disasters
- 2.1.2. Natural disasters
- 2.2. change of physical and psychological attributes 23
 - 2.2.1. Psychological situation 23
 - 2.2.2. physical situation 24
- 2.3. Re-construction after disaster 25

EXISTENCE OF HOME IN SETTLEMENT

A STUDY OF POST DISASTER HOUSING AT "TOTAGAMUWA"

List of Contents

- 2.3.1. center 25
- 2.3.2. enclosure 27
- 2.3.3. continuity 28
- 2.4. Resettlement/ Reconstruction after a Disaster-an Introduction 30
 - Transformation of Domestic Space
 - Transformation of Neighborhood
 - Transformation of the Village/ Community

Chapter 03

3. case study- Examination of the "Tsunami" disaster on Physical and Psychological attributes 34

- 3.1. selection of case study 34
- 3.2. method of conducting the case study 34
- 3.3. Examination of the "Tsunami" disaster on Physical and Psychological attributes
 - 3.3.1. historical background 39
 - 3.3.2. Present Situation **41**
 - 3.3.3. The disaster at Totagamuwa 46
 - 3.3.3.1. Location -01 (near the Colombo-Galle Road) 46
 - 3.3.3.2. Location -02(near the Rail way line) 55
 - 3.3.3.3. Location -03(near the Temple) 61

Conclusion 66

Bibliography 69



University of Moratuwa, Sri Lanka.
Electronic Theses & Dissertations
www.lib.mrt.ac.lk

Declaration

I declare that this dissertation represents my own work, except where due acknowledgement made, and that it has not been previously included in a thesis, dissertation or report submitted to the University or any other institution for a degree, diploma or other qualification.

UOM Verified Signature

Student Name,

Aseni H.D.A

Internal Tutor,

UOM Verified Signature

Prof. S. Manwa

Head (Dept. of Architecture), Faculty of Architecture, University of Moratuwa.



ACKNOWLEDGEMENTS

This Dissertation would never have been possible without the valuable support given by many, to whom I am indebted and thus sincerely acknowledge.

My gratitude is extended to Prof. Lakshman Alwis Prof. Nimal De Silva who guided me at the initial stages of this study.

Prof. S. Manawadu , Head, (Dept. of Architecture), for making background at the initial stages and giving guidance till the completion as my Tutor.

Archt. Vidura S. Nammuni, senior lecturer, who had given background knowledge throughout the academic years of university.

Dr. U. Rajepakse, 5th year masters and the coordinator of postgraduate architecture dissertations, for the guidance and incisive comments to make this a success.

Dr. H. Munasinghe , Senior Lecturer in Urban Architecture and; social and Behavioral studies, for filling me with different directions of topic selection.

Archt. Lilantha Wejepala, for the guidance, incisive comments, patience and inspiration given to me, and directing me towards many aspects of this study.



My deeper gratitude is extended Ven. Gammeddegoga Puññasāra for taught me a lot of historical Knowledge on Totagamuwa and Sri Lank.

I would like to offer my deep gratitude to my better half, Nalin for his help in field works, computer editing, preparation of sketches and far numerous advices, and courage to make this research a success. I would never have reached this level without his enormous support.

Also special thank would go to my friends, Minushi, Chandana, Dimal Ayya and his relatives ,Suresh, shamalee, Dilupa, Promadhi, Harshi, Suran, Amadhi and jouniors , Pudima and Pinto who helped me in taking photographs and sharing ideas giving me courage till the completion.



University of Moratuwa, Sri Lanka.

My Case studies would not have been successful, without the kind and cooperative help of the people at Tsunami early warning center, Totagamuwa villagers, who given me information's and shared their life experiences with me.

Finally, my most humble gratitude goes to my parents and sister who have consistently been my source of encouragement throughout my life.

Aseni H.D.A



EXISTENCE OF HOME IN SETTLEMENT
A STUDY OF POST DISASTER HOUSING AT "TOTAGAMUWA"
List of Contents

List of contents

Acknowledgement	i
Contents	ii
List of illustrations	iii
Introduction	iv
The study	
Need of the study	
Aims and Objectives of study	
Method of study	
Scope and limitation	

Chapter 01

1. Housing as a need of human existence	1
1.1. Need of "shelter"	1
1.1.1. "Shelter" as Dwelling	3
1.1.2. Meaning of Dwelling	4
1.1.3. Function of Dwelling	5
1.2. Home As center of Human Existence	6
1.2.1. Home in Built	6
1.2.1.1. Center	6
1.2.1.2. Enclosure	7
1.2.1.3. continuity	8

EXISTENCE OF HOME IN SETTLEMENT
A STUDY OF POST DISASTER HOUSING AT "TOTAGAMUWA"

List of Contents

1.3. psychological attributes of Home	9
1.3.1. personalization	9
1.3.2. sense of belongings	10
1.3.3. self esteem	11
1.3.4. status	11
1.3.5. identity	12
1.4. Physical attributes of Home	13
1.4.1. orientation	13
1.4.2. territoriality	14
1.4.3. security	14
1.4.4. privacy	15
1.5. formation of Physical and Psychological attributes	17
1.5.1. Socio-Cultural Background	17
1.5.2. Natural context	18
1.5.3. Economic and political background	19

Chapter 02

2. Disaster as event of social, physical and Psychological imbalance	20
2.1. Disaster	20
2.1.1. manmade disasters	21
2.1.2. Natural disasters	21
2.1.2.1. "Tsunami" a form of natural disaster	22
2.2. change of physical and psychological attributes	23
2.2.1. Psychological situation	23
2.2.2. physical situation	24
2.3. Re-construction after disaster	25

EXISTENCE OF HOME IN SETTLEMENT
A STUDY OF POST DISASTER HOUSING AT "TOTAGAMUWA"
List of Contents

2.3.1.	center	25
2.3.2.	enclosure	27
2.3.3.	continuity	28
2.4.	Resettlement/ Reconstruction after a Disaster-an Introduction	30
2.4.1.	Transformation of Domestic Space	30
2.4.2.	Transformation of Neighborhood	31
2.4.3.	Transformation of the Village/ Community	32
 Chapter 03		
3.	case study - Examination of the "Tsunami" disaster on Physical and Psychological attributes	34
3.1.	selection of case study	34
3.2.	method of conducting the case study	34
3.3.	Examination of the "Tsunami" disaster on Physical and Psychological attributes	
3.3.1.	historical background	39
3.3.2.	Present Situation	41
3.3.3.	The disaster at Totagamuwa	46
3.3.3.1.	Location -01(near the Colombo-Galle Road)	46
3.3.3.2.	Location -02(near the Rail way line)	55
3.3.3.3.	Location -03(near the Temple)	61
Conclusion		66
Bibliography		69



EXISTENCE OF HOME IN SETTLEMENT
A STUDY OF POST DISASTER HOUSING AT "TOTAGAMUWA"
List of Illustrations

List of Illustrations

Figure No	Description	Page
01.	The struggle of constricting a "shelter"	01
02.	Shelter provides a "Home to live..."	05
03.	Personalizing own home....	09
04.	Identity given...-Maori warriors Face	12
05.	"Vastu Purusha Mandala"	13
06.	Need of More security....-Old Dutch Warehouse @ Fort Colombo	14
07.	Not to See...from others	16
08.	Continuity of cultural Identities...-	17
09.	Natural Landscape formed the "Home" for monk with desired comfort levels.	18
10.	No Physical Environment Remained.....	22
11.	Damage of the Living Environment.....	22
12.	Psychological situation...	23
13.	All contaminated with pollutants	24
14.	Reconstruction of a New city center model of Rome	26
15.	Reconstruction of an enclosures Mecca... (S.Arabia) Ka'ba, at first houses clustered Close around the shrine	27



EXISTENCE OF HOME IN SETTLEMENT
A STUDY OF POST DISASTER HOUSING AT "TOTAGAMUWA"
List of Illustrations

16.	Reconstruction with continuity- Postdamer Platz renewal in Berlin, during construction in 1998	29
17.	Study Area of for the case Studies	35
18.	Totagamuwa-Temple	39
19.	Coir Trade- At Totagamuwa	42
20.	Fishing-Small Sail ships	42
21.	Children Gather Here and There..... No Ambitions for Life	44
22.	Pre- Disaster lay-out plan of Surroundings (Location-01)	46
23.	Activity Pattern-(Pre-Disaster) -Location-01	47
24.	The sketch from one the memory in mind	49
25.	Plan of the pre-disaster house Mr. Eric de Silva	50
26.	Post- Disaster lay-out plan of Surroundings	51
27.	Plan of Post-disaster House	52
28.	Post- Disaster lay-out plan of Surroundings	55
29.	Plan of pre-Disaster house-location-02	56
30.	Plan of the post-disaster house -location-02	58
31.	additional porch added to the house	59
32.	Demarcation of territoriality	59
33.	All the houses having same facade	60

EXISTENCE OF HOME IN SETTLEMENT
A STUDY OF POST DISASTER HOUSING AT "TOTAGAMUWA"
List of Illustrations

34.	layout Plan pre-disaster- Location -03	61
35.	layout Plan pre-disaster- Location -03	61
36.	Pre disaster house	62
37.	Post disaster house	62
38.	Dark ally ways in between houses	64
39.	Front façade of the setting	64



University of Moratuwa, Sri Lanka.
Electronic Theses & Dissertations
www.lib.mrt.ac.lk